


PORSE  
11.3.125.111  
NO DATE

# EPA - REQUEST QUESTION 37

## (FLOW DIAGRAM FOR GENERATED WASTE/DISPOSAL)

### TYPICAL

#### Manufacture of Forgings



Flow chart of typical operations in the production of hot forgings.

USEPA SF



1265365